

Problem	Inspection Suggestions	Potential Causes	Solutions
The handle latch is stuck in the open position.	- Operate the lockset from the interior side of the door repeatedly to see if the latch will extend Ensure the correct adapter is being used Ensure the PanoLock+ is centered in the boreholes Emtek lockset should have 2-piece adapter.	- Improper Panolock+ route of the door not allowing mortise box to operate freely Over tightening of screws of the lockset Incorrect handleset adapter used Adapter(s) is not installed correctly.	- Remove the interior side of the lockset, operate from the exterior side to see if latch will release and operate smoothly Reattach interior side of lockset without over tightening.
Electronic deadbolt lock does not function properly with PanoLock.	- Make sure lock system is Pano-Lock+ and not the original PanoLock. Look for a "+" after PanoLock on the faceplate. - Verify that the electric deadbolt is on the compatibility list.	- PanoLock 1.0 will not operate electronic deadbolts - Incorrect deadbolt adapter used PanoLock+ is not centered in the bore hole (bad route) Over tightening of the mounting screws.	- Follow the manufacturers' instructions on properly programming the electronic deadbolt Adjust screws if they are overtightened
PanoLock+ not working on Therma-Tru door panel.	- The PanoLock+ on Therma-Tru panel should be the model 1375 to accommodate their proud edge panel. The Panolock+ faceplate will measure 1-3/8" across.	- Lockset screws are overtightened Improper routing of the door panel edge Door panel thickness is less than 1-11/16".	- Back out lockset screws, at the same time, checking for correct functionality of Panolock+. - Completely remove the lockset and operate PanoLock+ with the construction handle to ensure proper operation.
Deadbolt tapered bolts engages when the door panel is bumped.	- Check that the correct deadbolt adapters are used and are inserted correctly Check that the deadbolt is installed correctly.	- Incorrect deadbolt adapter installed or inserted incorrectly. - Deadbolt lock spindle is not oriented to the manufacturer's specifications. - Malfunction in the drive rod of the Panolock+ mortise box.	- Review the latest compatability list and make sure the correct adapter has been used. - Orient the deadbolt spindle correctly into the neutral position, then insert into the adapter in the deadbolt drive.
Panolock+ Multi-point Locking System adapter ports are not centered in the preexisting deadbolt & handleset bore in door panel.	- Measure from the edge of the door to the center of boreholes to ensure it is 2-3/8" Boreholes should measure 5-1/2" center to center.	- PanoLock+ centering tool and rod were not used to route the door panel. - PanoLock+ only accommodates for a 2-3/8" backset.	A new door panel will need to be routed to the correct specifications using centering tool and rod if PanoLock+, with lockset, is not able to secure the opening.
Panolock+ bolts are not going into the roller strikes evenly.	- Check slab for warpage (string test or level) Check rough opening for level and plumb Inspect to see if adjustments to the rollers strikes can be made Inspect the strike mortises to ensure they are within specification per the mortising instructions.	- The slab is warped and will not align with strike plates The framed opening is not plumb so the bolts will not align Roller strike plates are out of adjustment Frame mortise dimensions are not correct causing the strike plate to not be in alignment.	- Slab replacement Have frame corrected by a professional contractor to plumb and/or correct machining Adjust the roller strike plates until proper tolerances are obtained Replace entire jamb or the entire jamb leg to correct frame machining specs.
Emtek deadbolt lock is not operating the upper and lower tapered bolts properly.	- Ensure that the Emtek deadbolt spacer ring has been installed Emtek deadbolt has an exterior keyhole cover Review that the correct deadbolt adapter used.	- Emtek deadbolt does not have a spacer ring Keyhole cover will not allow cylinder take a spacer ring Deadbolt is not removable from the faceplate to allow spacer ring Back of deadbolt cylinder is bottoming out internally, causing a grinding effect while turning.	- Deadbolt cylinder needs to be removed and the finished spacer ring applied to provide more space between cylinder and PanoLock Keyhole hole cover must be removed or the deadbolt lock has to be replaced.
Emtek thumbpress is not inserting into the split-square adapter properly.	- While viewing the inner side of thumbpress lock (right-side up), the spindle should appear square Ensure that he two-piece adapters for Emtek were correctly inserted and snapped fully into place.	- The spindle has been mis- assembled. The gear alignment will be visibly misaligned This is an Emtek defect.	- Customer must contact the Emtek lock supplier to submit a warranty claim. Emtek will send a half-lock replacement with corrected spindle orientation.