

Wood Veneer Astragal Repair Instructions

- 1** Lightly sand damaged area with 150-180 grit paper to smooth out bumps and burrs.




- 2** Apply "DAP Plastic Wood" brand repair filler to damaged area. Follow container instructions.



- 3** Finish wood veneer for exterior use.



*



DAP Plastic Wood

Veneer Species	DAP Color	UPC No.
Fir	Pine	7079821404
Mahogany	Walnut or Red Mahogany	7079821434 7079821424
Oak	Light Oak	7079821400
Pine	Pine	7079821404

* Other wood fillers may work, but require evaluation by the user.

 **Endura**

www.enduraproducts.com